

Oil Field Environmental Incident Summary

Incident: 20140701171340 **Date/Time of Notice:** 07/01/2014 17:13

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MEDICINE HOLE 14-27H

Field Name: JIM CREEK

Well File #: 16548

Date Incident: 7/1/2014 **Time Incident:** 10:00

Facility ID Number:

County: DUNN

Twp: 146

Rng: 96

Sec: 27

Qtr:

Location Description: Pasture, hayfield and cropland

Submitted By: Todd Senescall

Received By:

Contact Person: Ben Lemieux
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	5	Gallons

Recovered	Units
-----------	-------

Followup	Units
0.07	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/7/2016

Clean Up Concluded: 7/2/2014

Risk Evaluation:

fire

Areal Extent:

0.3 acres of pasture, 0.4 acres of cropland and 0.3 acres of hayfield were lightly misted with oil.

Potential Environmental Impacts:

no long term impacts expected to soil, none to surface or ground water

Action Taken or Planned:

Well shut in. Fire extinguished, New treater will be fitted with gaskets of different material. Misted pasture will be mowed and clippings bagged for disposal. Any remediation in the hayfield and cropland will be discussed with the landowner.

Wastes Disposal Location: tbd

Agencies Involved: Local Fire Department

Updates

Date: 7/2/2014 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 17:30. 72 degrees F, mostly sunny, calm wind. Observed site and took photos. Observations of the well pad and surrounding area showed that the heater/treater had caught on fire and had misted the vegetation to the south. The grasses to the south of the well pad and north of the lease road had been cut and placed in plastic bags (about 25 in a pile next to the heater/treater). The area cut and bagged was approximately 100' by 300' in size. Visual observations of the area indicated that the area cut and bagged showed very little to no impacts from the release. South of the lease road was rangeland directly south of the heater/treater and cropland approximately 250' to the east of the rangeland with no fence dividing each area. Observations of the trees/cropland/rangeland south of the lease road did not show any indications of the release. Follow up with phone call to company contact for confirmation of proper disposal of cuttings.

Date: 7/2/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Oil sprayed off location as a result of a treater fire. Follow-up is necessary.

Date: 6/29/2015 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The company provided a follow-up report and photo documentation that impacts have been removed and site has successfully re-vegetated. No further action is warranted at this time.

Date: 3/10/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.